

N.P.RY.			
TACOMA DIVISION		DISTANCE SCHEDULE	
COWICHE AND ROSLYN BRANCHES			
COWICHE BRANCH		<i>Distance between</i>	<i>Distance from Brace</i>
BRACE	Naches Branch Conn. H.B.(216+99 = 0+00)	0.000
	Station Sign (3+06 ⁷)	<u>0.058</u>
	To WEIKEL	4.899	
	Line betw. Val. Sec. #22 and #22 ^A (9+00)	0.170
			Val. Sec. <u>Wash. #22</u> <u>Wash. #22^A</u>
WEIKEL	Center of Shelter Shed (260+34 ⁵)	<u>4.957</u>
	To COWICHE	3.560	
COWICHE	Center of Shelter Shed (448+32 ¹)	<u>8.517</u>
	To HOLTZINGER	0.695	
HOLTZINGER	Station Sign (485+01)	<u>9.212</u>
	To TIETON	2.490	
TIETON	TASKER ... Hooker Co Spur H.B.(564+22)	10.710
	Yard Limit Sign-Tieton (590+00)	11.198
	Leg of Wye Conn. H.B.(599+06 = 0+00)	11.370
	Center of Depot (17+55)	<u>11.702</u>
	End of Branch (19+56 ⁵)	11.740
			253+53 = 252+13 ³
ROSLYN BRANCH		<i>Distance between</i>	<i>Distance from Cle Elum</i>
CLE ELUM	Main Line Conn. H.B.(8010+83 ⁸ = 0 - 42 ⁸)	0.000
	Center of Depot (0+72 ⁴)	<u>0.022</u>
	To MINE FIVE	2.004	
MINE FIVE	Line betw. Val. Sec. #2 and #2 ⁵ (27+80)	0.535
	Yard Limit Sign (31+94)	0.613
	Corporate Limit - Cle Elum (42+40)	0.811
	N.W.I. Co. Coal Washing Plant Conn. { H.B.(87+19 ⁵)	1.659
	Spur to Mine Five H.B.(104+37)	1.985
	To ROSLYN	1.461	
		Spur to Mine Nine H.B.(108+90)
ROSLYN	Corporate Limit - Roslyn (152+65)	2.899
	Center of Depot (183+71 ⁵)	<u>3.487</u>
	To RONALD	1.929	
	Corporate Limit - Roslyn (218+16)	4.140
RONALD	Center of Depot (285+55 ⁵)	<u>5.416</u>
	End of Branch (321+90 ⁵)	6.105