

N.P.RY.			
IDAHO DIVISION		DISTANCE SCHEDULE	
LAPWAI BRANCH (C.P.R.R.)			
		Distance between	Distance from Spalding
SPALDING	Palouse & Lewiston Branch Conn. H.B.(6683+84 ² = 0-13 ²)	0.000
	Center of Depot (2+30)	<u>0.046</u>
	To LAPWAI	3.303	
	Line betw. Val. Sec. #4 and #7 (16+71)	0.319
			Val. Sec. <u>Idaho #4</u> <u>Idaho #7</u>
LAPWAI	Corporate Limit - Fort Lapwai (154+18)	2.923
	Center of Depot (176+70 ²)	<u>3.349</u>
	To SWEETWATER	1.998	
	Corporate Limit - Fort Lapwai (177+62)	3.367
SWEETWATER	Station Sign (282+17 ²)	<u>5.347</u>
	To BUNDY	2.694	
BUNDY	Center of Shelter Shed (removed) (424+42 ²)	<u>8.041</u>
	To CULDESAC	4.054	
JACQUES ...	Spur H.B.(503+33 ²)	9.536
	Center of Shelter Shed (511+91)	9.698
CULDESAC	Corporate Limit - Culdesac (626+74 ²)	11.873
	Center of Depot (638+48 ²)	<u>12.095</u>
	To NUCRAG	7.409	
	Corporate Limit - Culdesac (660+26)	12.508
	Line betw. Nez Perce and Lewis Counties (952+70)	18.046
NUCRAG	Station Sign (1029+69)	<u>19.504</u>
	To REUBENS	6.636	
Tunnel #1	{ East Portal (1059+42 ²)	20.068
	{ West Portal (1068+25)	20.235
Tunnel #2	{ East Portal (1128+75)	21.380
	{ West Portal (1129+64 ²)	21.397
Tunnel #3	{ East Portal (1161+82)	22.006
	{ West Portal (1167+44 ²)	22.113
	Line betw. Lewis and Nez Perce Counties .. (1176+00)	22.275
Tunnel #4	{ East Portal (1200+56)	22.740
	{ West Portal (1202+69)	22.781

N.P.RY.			
IDAHO DIVISION		DISTANCE SCHEDULE	
LAPWAI BRANCH (C.P.R.R.)			
		<i>Distance between</i>	<i>Distance from Spalding</i>
	Tunnel #5	{ East Portal (1224+88)	23.201
		{ West Portal (1227+30)	23.247
	Tunnel #6	{ East Portal (1246+62)	23.613
		{ West Portal (1251+83)	23.712
	Tunnel #7	{ East Portal (1270+04 ⁵)	24.056
		{ West Portal (1275+16)	24.153
	Line betw. Nez Perce and Lewis Counties and Corporate Limit - Reubens (1372+14 ²)		25.989
REUBENS	Center of Depot (1380+05 ²)		<u>26.140</u>
	To CRAIG JCT.	3.924	
	Corporate Limit - Reubens (1401+57 ⁴)		26.548
	Clicks ... Spur H.B.(1561+49 ⁵)		29.576
CRAIG JCT	Center of Shelter Shed (1587+25 ¹)		<u>30.064</u>
	To CRAIGMONT	4.370	
	Corporate Limit - Craigmont (1802+08)		34.133
CRAIGMONT	Center of Depot (1817+98)		<u>34.434</u>
	To FERDINAND	7.884	
	Corporate Limit - Craigmont (1826+39)		34.593
	Nezperce R.R. Conn. H.B.(1843+13 ³)		34.910
	Line betw. Lewis and Idaho Counties (2017+28 ⁸)		38.209
FERDINAND	Center of Depot (2234+26)		<u>42.318</u>
	To COTTONWOOD	8.679	
	Sand Spur H.B.(2413+85 ²)		45.720
	Rock Quarry Spur H.B.(2567+96 ⁸)		48.638
COTTONWOOD	Corporate Limit - Cottonwood (2652+35)		50.237
	Center of Depot (2692+51 ²)		<u>50.997</u>
	To FENN	8.517	
	Corporate Limit - Cottonwood (2727+08)		51.652
FENN	Center of Depot (3142+18 ³)		<u>59.514</u>
	To GRANGEVILLE	7.047	
	Prairie Lbr. Co. Spur H.B.(3467+78)		65.680
GRANGEVILLE	Corporate Limit - Grangeville (3500+59 ⁵)		66.302
	Center of Depot (3514+26 ⁵)		<u>66.561</u>
	End of Branch (3526+23)		66.787

Shelter Shed property of Craig Lbr. Co.