

N.P.RY.
YELLOWSTONE DIVISION **DISTANCE SCHEDULE**
LAKE BASIN BRANCH

		<i>Distance between</i>	<i>Distance from Mossmain</i>	
MOSSMAIN	Main Line Conn. H.B.(614+64 = 0+04 ⁴)	0.000	
	End of N.P.Ry. and beg. of G.N.Ry. (1+20 N.P.= 1111+72 G.N)	0.022	
	Center of Depot (1108+65)	<u>0.080</u>	
	To HESPER	4.040		
	Yard Limit Sign (1051+22)	1.168	909 - 910 = 46'
HESPER	End of G.N.Ry. and beg. of N.P.Ry. Lake Basin Branch. H.B.(899+69 ⁴ G.N.= 0-104 ⁷ N.P.)	4.027	Val. Sec. Mont. * 20
	Center of Depot (3+84)	<u>4.120</u>	
	To WICKETT	4.196		92+19 ⁵ = 92+10 ² 189+87 ² = 189+11
WICKETT	Station Sign (224+54 ²)	<u>8.316</u>	
	To COOMBS	9.534		395+39 ⁶ = 396+40 ²
COOMBS	Line betw. Yellowstone and Stillwater Counties (541+74)	14.304	607+23 ² = 606+48 ²
	Station Sign (728+18)	<u>17.850</u>	
	To MOLT	6.076		864+70 ² = 866+67 981+64 ⁵ = 981+68 ⁵
MOLT	Center of Depot (1051+01 ²)	<u>23.926</u>	1072+72 ⁴ = 1072+82 ⁵
	To WHEAT BASIN	7.829		1340+37 ² = 1338+10 ⁷
WHEAT BASIN	Station Sign (1462+23 ⁶)	<u>31.755</u>	
	To RAPELJE	10.105		1593+24 ¹ = 1098+89 ¹
RAPELJE	Center of Depot (1501+44)	<u>41.860</u>	
	End of Branch (1519+35 ²)	42.200	