

N.P.RY.			
YELLOWSTONE DIVISION		DISTANCE SCHEDULE	
ROSEBUD AND BILLINGS & CENTRAL MONTANA BRANCHES			
ROSEBUD BRANCH		Distance between	Distance from Nichols
NICHOLS	Main Line Conn. H.B.(6833+60 ² =0-1094 ²) To DOWLIN	14.882	0.000
			Val. Sec. Mont. #24
			105 - 106 = 108' 188 - 189 = 107' 209 - 210 = 99' 275 - 276 = 94' 349+54 ² = 349+95' 410 - 411 = 176' 528 - 529 = 99' 534 - 535 = 94' 721 - 722 = 91'
DOWLIN	Station Sign (774+53) To COLSTRIP	14.622	14.882
			875 - 876 = 112' 912 - 913 = 96' 944 - 945 = 104' 1016 - 1017 = 104' 1133 - 1134 = 92' 1398 - 1399 = 173'
	Yard Limit Sign - Colstrip (1463+60)		27.948
	Cow Creek Line Conn. H.B.(1541+03 ¹)		29.416
COLSTRIP	Center of Depot (1545+70)		29.504
	End of Branch (1603+75)		30.604
	Cow Creek Center of Yard Office (1774+37 ⁵)		33.840
			1551+70 ⁵ = 1551+276 C.C. Line 1724+85 = 1725+088 C.C. Line 1746+52 = 1746+50 C.C. Line
BILLINGS & CENTRAL MONTANA BRANCH			Distance from Billings
BILLINGS	Main Line Conn. H.B.(11890+32 ¹ = 0+00) To M ⁵ CRACKEN	4.037	0.000
	End of N.P.Ry. and beg. of C.B.&Q.R.R. (3+04 NP = 1180+41 ⁵ C.B.&Q)		0.058
	Initial point of B.&C.M.Ry. (1124+23 ⁵ = 0+00)		1.122
	End of C.B.&Q.R.R. and beg. of N.P.Ry. (15+63 ¹)		1.418
	Yard Limit Sign - Billings (137+40)		2.602
			Val. Sec. Mont. #22
M ⁵ CRACKEN	Station Sign (153+93 ⁸) To CLINE	4.586	4.037
CLINE	G.W. Sugar Co. Spur H.B. (396+06 ⁸) To SHEPHERD	5.121	8.623
SHEPHERD	Center of Beet Platform (666+45 ⁸)		13.744
	End of Branch (675+77)		13.920