

HUMPHREY, WASHINGTON.

T-1

Seattle Division.

| A.F.E.   | E.D.  | F.C.R. | DESCRIPTION.                            |
|----------|-------|--------|---|
| 562-A-31 | 84-31 | 10915  | Replace Foundation under Section House. |

Tacoma Division.

|          |        |       |  |
|----------|--------|-------|--|
| 277-34   | 66-34  |       | Mud Slide Detector Fence at M.P. 70+1469'.   |
| 203-35   | 54-35  | 11899 | Rip Rap at M.P. 70+1235'.                    |
| 582-36   | 131-36 | 12480 | Extend spurs to serve Baker-Knapp Lumber Co. |
| 669-37   | 168-37 | 12995 | Replace Water Supply Pipe.                   |
| 303-A-39 | 71-39  | 13507 | Toilet.                                      |
| 416-A-39 | 94-39  | 13246 | Shelter Shed.                                |
| 746-40   | 157-40 | 13698 | Relay portion of Passing Track.              |
| 688-48   | 150-48 | 15898 | Shorten Siding at East End.                  |
| 315-54   | 56-54  | 16957 | Construct Crossover. ( Cancelled )           |
| 376-A-59 | 50-59  |       | Retirements Account of Dieselization.        |
| 154-A-62 | 1-62   | 19791 | Sale & Removal of Section House.             |