

RESERVATION.
Tacoma Division.

A.F.E.	E.D.	F.C.R.	DESCRIPTION.
197-A-34	6-34	11722	Relay Curve # 38, Southbound. Val.Sec'n. 3.
197-B-34	6-34		Relay Curve # 38, Southbound. Val.Sec'n. 4.
519-34	132-34	11700	Overhead Highway Bridge at M.P. 37+4692'.
588-A&B-34	165-34	11678&11679	Restore and Repair Road Bed at M.P. # 38.
416-E-39	94-39		Replace Toilet at Interlocker.
657-40	142-40		Replace Color Light Home Signals #1 and #2 at Interlocker.
184-42	29-42	14139	Relay Curves.
109-43	52-43		Changes at Interlocking Plant.
755-51	166-51	16390	Place Rip Rap to Prevent Erosion.
767-51	168-51	16433	Changes to Interlocking Plant.
166-52	29-52	16990	84" Tunnel Liner Culvert at M.P. 37+2963'. (Cancelled 1019-54)
403-56	90-56	17423	Replace Cast Iron Pipe Culvert with R.C.P. at M.P. 36+2393'.
342-62	52-62	19430	Relay Curve -E.B.M.L.
633-66	112-66		Replace Crossing at 6th. Ave. North
101-A-66	1-66	20842	Extend spur track.